407-431 West Lexington Street (Lexington Market Addition)
409 West Lexington Street (Commercial Building)
Baltimore (Independent City)
Maryland

HABS No. MD-916-B

HABS MD, H-BALT, 157B-

## **PHOTOGRAPHS**

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
MID-ATLANTIC REGION NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
PHILADELPHIA, PENNSYLVANIA 19106

Form 10-920 (June 1983)

COMPILER, AFFILIATION

Corporation, Baltimore

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS MD, 4-BALT, 157B-

DATE

August 1981

## ARCHITECTURAL DATA FORM

				1510	
STATE	COUNTY		TOWN OR VICINITY		
Maryland			Baltimore (	(Independent City)	
HISTORIC NAME OF STRUCTURE (INCL	UDE SOURCE FOR	NAMEL		HABS NO.	
407-431 West Lexington Street					
				MD-916-B	
SECONDARY OR COMMON NAMES OF	TRUCTURE				
Lexington Market Additio					
409 West Lexington Stree					
COMPLETE ADDRESS (DESCRIBE LOCAL		S//ES)			
. 409 West Lexington Street					
DATE OF CONSTRUCTION (INCLUDE S	OURCE)	ARCHITECT(S) (INC.	LUDE SOURCE)	<del></del>	
circa 1855		Unknown, probably none			
			· · · · · · · · · · · · · · · · · · ·		
SIGNIFICANCE (ARCHITECTURAL AND				_	
Was a good example of mid					
in the block frontage that faced Lexington Market. Architectural significance has been diminished by alteration to facade. Probably had retail use at ground floor,					
STYLE (IF APPROPRIATE) residence	e above.	. ITODADIY Had A	ictail use at a	, round ricor,	
Federal-Greek Revival tow	mhouse (altere	d)			
MATERIAL OF CONSTRUCTION (INCLU	IDE STRUCTURAL	SYSTEMS)			
Brick (5:1 common bond), slate roof, timber floor and roof system					
APE AND DIMENSIONS OF STRUCTU	·			·	
Rectangular, 16' x 66' wi	th later rear	additions; roof	ridge of gable	e parallel to	
EXTERIOR FEATURES OF NOTE					
Dentiled cornice partial1	y hidden by la	ter facade; gable	ed roof dormers	, front and	
rear; remainder of front	facade hidden	by later alterat:	ion		
INTERIOR FEATURES OF NOTE (DESC!	RIBE FLOOR PLANS	S, IF NOT SKETCHED)			
Interior gutted for retai	l use at first	floor; minor two	panel doors i	n second	
level, and period trim					
MAJOR ALTERATIONS AND ADDITION		\. gooond ========	Adition oires	1020 (man	
Rear addition, circa 1900 (map research); second rear addition, circa 1920 (map research); aluminum front facade circa 1960s					
researchy, aruminum front	. Lacade CIICA	17000			
PRESENT CONDITION AND USE			F**** - A1		
Fair condition; last use	retail, now va	cant			
OTHER INFORMATION AS APPROPRIA	TE				
<u> </u>					
SOURCES OF INFORMATION (INCLUDIA	NG LISTING ON NA	TIONAL REGISTER, S	TATE REGISTERS, E	ETC.)	
1980 Survey of the Baltimore Central Business District					
<u></u>					

Russell Wright, AIA, Consultant, Market Center Development